

State of California -- The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 312 E. BERNA AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 312 E. BERNA AVE City NAPA Zip 945592028

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 045161013000

*P3a. Description:

- Style(s): Minimal Traditional
- Stories: 2
- Cladding: brick, smooth stucco
- Porch: partial width, recessed, wood posts, wood rail
- Door(s): single, door material unknown
- Windows: Type 1 - tripartite, double hung, material unknown, fixed, wood; Type 2 - single, double hung, material unknown; Type 3 - single, sliding, vinyl
- Roof: cross hipped, composition shingle, intersecting gable at ridgeline, open eaves
- Chimney: none visible
- Related Features: attached 1-car garage
- Alterations: addition to rear elevation, some windows replaced
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

South elevation

ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1950, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: April 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):

DPR 523A (1/95)

*Required Information

PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 314 E. BERNA AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 314 E. BERNA AVE City NAPA Zip 95436

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 045161012000

*P3a. Description:

- Style(s): American Colonial Revival
- Stories: 2
- Cladding: wood lap
- Porch: entrance porch, concrete steps, pierced iron rail
- Door(s): single, door material unknown, metal screen
- Windows: Type 1 - single, double hung, wood, shutters; Type 2 - single, double hung, wood
- Roof: side gable, composition shingle, open eaves
- Chimney: none visible
- Related Features: attached 1-car garage
- Alterations: none visible
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

South elevation
ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both
1950, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.
Pier 9, The Embarcadero
San Francisco, California 94111

*P9. Date Recorded: April 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic
Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) *Required Information

State of California -- The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 316 E. BERNA AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 316 E. BERNA AVE City NAPA Zip 945592028

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 045161011000

*P3a. Description:

- Style(s): Minimal Traditional
- Stories: 1
- Cladding: wood clapboards
- Porch: partial width, recessed, stone veneer steps, wood posts, wood rail
- Door(s): single, door material unknown, metal screen
- Windows: Type 1 - paired, double hung, material unknown; Type 2 - single, fixed, vinyl
- Roof: cross gable, composition sheets, open eaves
- Chimney: brick, exterior
- Related Features: detached 2-car garage
- Alterations: some windows replaced
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

South elevation
ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both
1950, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.
Pier 9, The Embarcadero
San Francisco, California 94111

*P9. Date Recorded: April 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic
Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) ***Required Information**

State of California -- The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 318 E. BERNA AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 318 E. BERNA AVE City NAPA Zip 945592028

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 045161010000

*P3a. Description:

- Style(s): Minimal Traditional
- Stories: 1
- Cladding: aluminum
- Porch: entrance porch, concrete steps, pierced iron rail
- Door(s): single, door material unknown, metal screen
- Windows: Type 1 - single, sliding, aluminum; Type 2 - double hung, aluminum
- Roof: cross gable, composition shingle, open eaves
- Chimney: brick, exterior
- Related Features: detached 2-car garage
- Alterations: cladding altered, awnings incompatible, windows replaced
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

South elevation
ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both
1943, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.
Pier 9, The Embarcadero
San Francisco, California 94111

*P9. Date Recorded: April 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic
Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) ***Required Information**

State of California -- The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 431 E. BERNA AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 431 E. BERNA AVE City NAPA Zip 945592005

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 045162006000

*P3a. Description:

- Style(s): Minimal Traditional
- Stories: 1
- Cladding: smooth stucco
- Porch: entrance porch, partial width, wood posts
- Door(s): single, door material unknown, metal screen
- Windows: Type 1 - paired, double hung, aluminum
- Roof: cross gable, composition shingle
- Chimney: none visible
- Related Features: carport
- Alterations: House is on a site slightly lower than the street level. The carport pad built was added at level of sidewalk., carport added
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:
North elevation
ARG, January 2011

*P6. Date Constructed/Age and Source:
 Historic Prehistoric Both
1940, Napa City & County records

*P7. Owner and Address:
Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis
Architectural Resources Group, Inc.
Pier 9, The Embarcadero
San Francisco, California 94111

*P9. Date Recorded: April 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic
Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) ***Required Information**

State of California -- The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 445 E. BERNA AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 445 E. BERNA AVE City NAPA Zip 94558

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 045162007000

*P3a. Description:

- Style(s): Minimal Traditional / American Colonial Revival
- Stories: 1
- Cladding: smooth stucco
- Porch: entrance porch, wood posts
- Door(s): single, wood, paneled
- Windows: Type 1 - paired, double hung, wood, shutters
- Roof: side gable, composition sheets
- Chimney: brick, exterior
- Related Features: attached 1-car garage
- Alterations: none visible
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

North elevation

ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1950, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: April 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) ***Required Information**

PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 455 E. BERNA AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 455 E. BERNA AVE City NAPA Zip 94559

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) _____ APN 045162008000

*P3a. Description:

- Style(s): Minimal Traditional
- Stories: 1
- Cladding: textured stucco
- Porch: partial width, recessed, concrete steps, wood posts
- Door(s): single, wood, paneled; Secondary - double, wood, partially glazed
- Windows: Type 1 - single, double hung, wood, multipane
- Roof: cross gable, composition shingle, open eaves
- Chimney: none visible
- Related Features: attached 1-car garage
- Alterations: door replaced, some windows replaced, some window openings resized, porch altered, Porch partially enclosed by a concrete masonry unit wall., CMU wall added, divides driveway from front yard
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

North elevation

ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1945, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: April 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):

PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 456 E. BERNA AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 456 E. BERNA AVE City NAPA Zip 945592028

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 045161009000

*P3a. Description:

- Style(s): Minimal Traditional
- Stories: 1
- Cladding: smooth stucco
- Porch: partial width, recessed, stone veneer steps, wood posts, wood rail
- Door(s): single, door material unknown, wood screen
- Windows: Type 1 - grouped, double hung, vinyl, shutters; Type 2 - single, double hung, vinyl, shutters; Type 3 - grouped, double hung, vinyl
- Roof: cross gable, composition shingle, open eaves
- Chimney: brick, exterior
- Related Features:
- Alterations: windows replaced
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

East elevation

ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1941, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: April 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) ***Required Information**

PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6L

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1005 CLARK ST

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1005 CLARK ST City NAPA Zip 945591454

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 006392004000

*P3a. Description:

- Style(s): Ranch, American Colonial
- Stories: 1
- Cladding: brick, smooth stucco
- Porch: entrance porch, concrete steps, iron rail
- Door(s): single, wood, paneled, historic surround
- Windows: Type 1 - rounded bay, casement, fixed, wood, multipane; Type 2 - single, double hung, wood, shutters; Type 3 - single, casement, steel
- Roof: side gable, composition sheets, open eaves
- Chimney: brick, interior
- Related Features:
- Alterations: none visible
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:
North elevation
ARG, January 2011

*P6. Date Constructed/Age and Source:
 Historic Prehistoric Both
1957, Napa City & County records

*P7. Owner and Address:
Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis
Architectural Resources Group, Inc.
Pier 9, The Embarcadero
San Francisco, California 94111

*P9. Date Recorded: January 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic
Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) *Required Information

PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1009 CLARK ST

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1009 CLARK ST City NAPA Zip 94558

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 006392005000

*P3a. Description:

- Style(s): Victorian, Vernacular Cottage, hip roof
- Stories: 1
- Cladding: wood clapboards
- Porch: none
- Door(s): single, wood, paneled
- Windows: Type 1 - single, sliding, aluminum; Type 2 - paired, double hung, wood, historic surround
- Roof: hipped, composition sheets, boxed eaves
- Chimney: none visible
- Related Features: shed
- Alterations: porch enclosed
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

North elevation

ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1910, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: January 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) *Required Information

State of California -- The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1014 CLARK ST

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1014 CLARK ST City NAPA Zip 94559

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 045013008000

*P3a. Description:

- Style(s): Minimal Traditional
- Stories: 1
- Cladding: wood clapboards
- Porch: entrance porch, brick steps, iron rail
- Door(s): single, wood, paneled, metal screen; Secondary - single, wood, divided lights, partially glazed, paneled, metal screen
- Windows: Type 1 - single, double hung, vinyl, historic surround; Type 2 - paired, double hung, vinyl, historic surround
- Roof: side gable, composition shingle
- Chimney: brick, exterior
- Related Features: detached 1-car garage
- Alterations: windows replaced
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:
South elevation
ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1939, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: January 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) ***Required Information**

PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1015 CLARK ST

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1015 CLARK ST City NAPA Zip 945591454

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 006392006000

*P3a. Description:

- Style(s): Minimal Traditional
- Stories: 1
- Cladding: smooth stucco
- Porch: partial width, brick steps, wood posts
- Door(s): single, door material unknown, metal screen
- Windows: Type 1 - single, fixed, steel; Type 2 - single, casement, steel
- Roof: cross gable
- Chimney: brick, interior
- Related Features:
- Alterations: none visible
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

North elevation
ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1948, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: January 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) *Required Information

PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1016 CLARK ST

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1016 CLARK ST City NAPA Zip 945591455

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 006391005000

*P3a. Description:

- Style(s): Minimal Traditional
- Stories: 1
- Cladding: wood drop channel
- Porch: partial width, concrete steps, wood posts, iron rail
- Door(s): single, wood, paneled, metal screen
- Windows: Type 1 - tripartite, double hung, fixed, vinyl; Type 2 - single, fixed, wood, multipane; Type 3 - single, double hung, vinyl
- Roof: hipped, composition sheets, exposed rafter tails
- Chimney: brick, interior
- Related Features: detached 2-car garage
- Alterations: some windows replaced
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:
South elevation
ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both
1949, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: January 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) *Required Information

State of California -- The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1018 CLARK ST

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1018 CLARK ST City NAPA Zip 945584622

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 006391006000

*P3a. Description:

- Style(s): Minimal Traditional
- Stories: 1
- Cladding: textured stucco
- Porch: entrance porch, recessed, brick steps
- Door(s): single, wood, metal screen
- Windows: Type 1 - single, double hung, vinyl; Type 2 - single, fixed, leaded glass; Type 3 - grouped, double hung, vinyl
- Roof: cross gable, composition shingle, exposed rafter tails, open eaves
- Chimney: brick, interior
- Related Features: detached 1-car garage
- Alterations: windows replaced
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

South elevation

ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1940, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: January 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) ***Required Information**

PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6L

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1019 CLARK ST

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1019 CLARK ST City NAPA Zip 94559

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 006392007000

*P3a. Description:

- Style(s): Ranch, Traditional
- Stories: 1
- Cladding: wood clapboards
- Porch: recessed, brick steps, wood posts, wood turned posts
- Door(s): single, wood, paneled
- Windows: Type 1 - single, double hung, wood, shutters
- Roof: cross gable, composition shingle, open eaves
- Chimney: none visible
- Related Features: attached 1-car garage
- Alterations: none visible
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

North elevation

ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1950, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: January 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) *Required Information

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1020 CLARK ST

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1020 CLARK ST City NAPA Zip 94559

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 006391001000

***P3a. Description:**

- Style(s): Minimal Traditional
- Stories: 1
- Cladding: wood clapboards
- Porch: partial width, concrete steps, wood posts, iron rail
- Door(s): single, door material unknown, metal screen; Secondary - single, wood, partially glazed
- Windows: Type 1 - tripartite, double hung, fixed, vinyl, historic surround; Type 2 - single, double hung, vinyl, historic surround
- Roof: side gable, composition shingle, open eaves
- Chimney: wood, exterior
- Related Features: detached 1-car garage
- Alterations: windows replaced
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

South elevation
ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both
1941, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.
Pier 9, The Embarcadero
San Francisco, California 94111

*P9. Date Recorded: January 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic
Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) ***Required Information**

State of California -- The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6L
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1022 CLARK ST

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1022 CLARK ST City NAPA Zip 945581735

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 006391002000

*P3a. Description:

- Style(s): Minimal Traditional
- Stories: 1
- Cladding: textured stucco
- Porch: partial width, recessed, concrete steps, iron rail
- Door(s): single, door material unknown, metal screen
- Windows: Type 1 - canted bay, double hung, wood, multipane top sash; Type 2 - single, double hung, wood; Type 3 - tripartite, double hung, fixed, wood; Type 4 - paired, double hung, wood
- Roof: cross gable, composition sheets, exposed rafter tails, open eaves
- Chimney: stucco, interior
- Related Features: detached 1-car garage
- Alterations: none visible
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

South elevation

ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1930, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: January 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):

DPR 523A (1/95)

*Required Information

State of California -- The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1023 CLARK ST

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1023 CLARK ST City NAPA Zip 945591454

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 006392008000

*P3a. Description:

- Style(s): Ranch, Minimal
- Stories: 1
- Cladding:
- Porch: entrance porch, concrete steps, wood posts
- Door(s): single, wood
- Windows: Type 1 - single, double hung, vinyl
- Roof: cross hipped, composition shingle
- Chimney: brick, exterior
- Related Features: attached 1-car garage
- Alterations: windows replaced
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

North elevation

ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1950, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: January 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) ***Required Information**

PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1024 CLARK ST

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1024 CLARK ST City NAPA Zip 94558

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 006391003000

*P3a. Description:

- Style(s): English Revival, Tudor
- Stories: 1
- Cladding: smooth stucco
- Porch: entrance porch, concrete steps, iron rail
- Door(s): single, wood, paneled
- Windows: Type 1 - single, fixed, vinyl; Type 2 - single, double hung, vinyl
- Roof: cross gable, composition shingle
- Chimney: none visible
- Related Features: detached 1-car garage
- Alterations: windows replaced
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

South elevation
ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both
1938, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.
Pier 9, The Embarcadero
San Francisco, California 94111

*P9. Date Recorded: January 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic
Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) *Required Information

PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1025 CLARK ST

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1025 CLARK ST City NAPA Zip 945591454

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 006392001000

*P3a. Description:

- Style(s): Ranch, Contemporary
- Stories: 1
- Cladding: brick, smooth stucco, wood clapboards
- Porch: none
- Door(s): single, wood, paneled
- Windows: Type 1 - single, sliding, vinyl
- Roof: hipped, composition sheets, wide eaves
- Chimney: wood, interior
- Related Features: carport
- Alterations: windows replaced
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:
North elevation
ARG, January 2011

*P6. Date Constructed/Age and Source:
 Historic Prehistoric Both
1954, Napa City & County records

*P7. Owner and Address:
Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis
Architectural Resources Group, Inc.
Pier 9, The Embarcadero
San Francisco, California 94111

*P9. Date Recorded: January 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic
Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) *Required Information

State of California -- The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1029 CLARK ST

P1. Other Identifier: _____

***P2. Location:** Not for Publication Unrestricted

***a. County** Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

***b. USGS 7.5' Quad** _____ **Date** _____ **T** _____; **R** _____; **1/4 of** _____ **1/4 of Sec** _____; _____ **B.M.**

c. Address 1029 CLARK ST **City** NAPA **Zip** 945591454

d. UTM: (Give more than one for large and/or linear resources) **Zone** _____, _____ **mE/** _____ **mN**

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) _____ **APN** 006392002000

***P3a. Description:**

- Style(s): Ranch, Contemporary
- Stories: 1
- Cladding: concrete block
- Porch: entrance porch, recessed, brick steps
- Door(s): wood, metal screen
- Windows: Type 1 - casement, steel
- Roof: hipped, composition shingle, open eaves, wide eaves
- Chimney: none visible
- Related Features: attached 2-car garage
- Alterations: none visible
- Notes:

***P3b. Resource Attributes:** (List attributes and codes) HP2. Single family property

***P4. Resources Present:** Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

North and east elevations

ARG, January 2011

***P6. Date Constructed/Age and Source:**

Historic Prehistoric Both

1951, Napa City & County records

***P7. Owner and Address:**

Not recorded

***P8. Recorded by:** K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

***P9. Date Recorded:** January 2011

***P10. Survey Type:** Intensive

***P11. Report Citation:** Alta Heights Historic

Context Statement and Survey Report

***Attachments:** NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) ***Required Information**

PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1030 CLARK ST

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1030 CLARK ST City NAPA Zip 945591449

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 006394007000

*P3a. Description:

- Style(s): English Revival, Tudor
- Stories: 1
- Cladding: textured stucco
- Porch: entrance porch, concrete steps, wood rail
- Door(s): single, wood, paneled; Secondary - single, wood, partially glazed, paneled
- Windows: Type 1 - tripartite, double hung, fixed, vinyl; Type 2 - single, double hung, vinyl
- Roof: cross gable, composition shingle
- Chimney: brick, exterior
- Related Features: detached 2-car garage
- Alterations: cladding altered, windows replaced
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

West and south elevations
ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1938, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: January 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) *Required Information

State of California -- The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1033 CLARK ST

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1033 CLARK ST City NAPA Zip 94559

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 006393004000

*P3a. Description:

- Style(s): Minimal Traditional
- Stories: 1
- Cladding: textured stucco
- Porch: partial width, concrete steps, wood posts, iron rail
- Door(s): single, wood, paneled
- Windows: Type 1 - single, fixed, material unknown; Type 2 - single, double hung, vinyl; Type 3 - single, sliding, vinyl
- Roof: side gable, composition shingle, brackets, open eaves, wide eaves
- Chimney: none visible
- Related Features: detached 2-car garage
- Alterations: cladding altered, windows replaced, garage door replaced
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

North elevation

ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1926, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: January 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) ***Required Information**

State of California -- The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6L
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1035 CLARK ST

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1035 CLARK ST City NAPA Zip 945591448

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 006302001000

*P3a. Description:

- Style(s): Ranch, Contemporary
- Stories: 1
- Cladding: board and batten, fieldstone
- Porch: entrance porch, recessed, stone steps
- Door(s): single, wood, sidelights
- Windows: Type 1 - tripartite, fixed, sliding, aluminum; Type 2 - single, sliding, aluminum
- Roof: cross gable, vergeboards, open eaves, wide eaves
- Chimney: stone, exterior
- Related Features: detached 2-car garage
- Alterations: Garage door replaced
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

North elevation

ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1965, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: January 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) ***Required Information**

State of California -- The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1036 CLARK ST

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1036 CLARK ST City NAPA Zip 94574

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 006394008000

*P3a. Description:

- Style(s): Ranch, Traditional
- Stories: 1
- Cladding: wood clapboards
- Porch: partial width, wood posts
- Door(s): single, wood, divided lights, partially glazed, paneled
- Windows: Type 1 - single, casement, vinyl; Type 2 - grouped, casement, vinyl
- Roof: cross gable, composition shingle, exposed rafter tails, open eaves
- Chimney: none visible
- Related Features: attached 1-car garage
- Alterations: windows replaced
- Notes: also APNs 006394009000, 006394010000

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

South elevation
ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both
c. 1940, architectural estimate

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.
Pier 9, The Embarcadero
San Francisco, California 94111

*P9. Date Recorded: January 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic
Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) ***Required Information**

PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1037 CLARK ST

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1037 CLARK ST City NAPA Zip 94118

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 006302002000

*P3a. Description:

- Style(s): Minimal Traditional
- Stories: 1
- Cladding: smooth stucco
- Porch: entrance porch, concrete steps, wood posts
- Door(s): single, wood, partially glazed, paneled
- Windows: Type 1 - single, double hung, vinyl
- Roof: side gable, composition shingle
- Chimney: none visible
- Related Features: detached 1-car garage
- Alterations: windows replaced
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:
North elevation
ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1950, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: January 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) *Required Information

PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1039 CLARK ST

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1039 CLARK ST City NAPA Zip 94559

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 006302003000

*P3a. Description:

- Style(s): Modernism, Mid-Century
- Stories: 1
- Cladding: textured stucco
- Porch: entrance porch, tile steps, stucco posts
- Door(s): single, wood, paneled
- Windows: Type 1 - tripartite, fixed, sliding, vinyl; Type 2 - single, sliding, vinyl
- Roof: flat, material not visible, wide eaves
- Chimney: none visible
- Related Features: carport
- Alterations: cladding altered, windows replaced, porch altered, appears largely altered
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

North elevation
ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1953, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: January 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) *Required Information

State of California -- The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1040 CLARK ST

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1040 CLARK ST City NAPA Zip 94559

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 006301008000

*P3a. Description:

- Style(s): Minimal Traditional
- Stories: 1
- Cladding: brick, smooth stucco
- Porch: entrance porch, concrete steps
- Door(s): single, wood; Secondary - single, wood, partially glazed
- Windows: Type 1 - single, sliding, aluminum
- Roof: hipped, composition shingle, open eaves
- Chimney: brick, exterior
- Related Features: carport
- Alterations: none visible
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

South elevation
ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both
1957, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.
Pier 9, The Embarcadero
San Francisco, California 94111

*P9. Date Recorded: January 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic
Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) ***Required Information**

State of California -- The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1041 CLARK ST

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1041 CLARK ST City NAPA Zip 945591448

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 006302004000

*P3a. Description:

- Style(s): Minimal Traditional
- Stories: 1
- Cladding:
- Porch: entrance porch, concrete steps, wood posts, wood rail
- Door(s): single, wood, divided lights, partially glazed
- Windows: Type 1 - single, sliding, vinyl
- Roof: front gable, composition shingle, open eaves
- Chimney: brick, exterior
- Related Features: attached 1-car garage
- Alterations: cladding altered, windows replaced
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:
North elevation
ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1950, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: January 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) ***Required Information**

State of California -- The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1043 CLARK ST

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1043 CLARK ST City NAPA Zip 945591448

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 006302005000

*P3a. Description:

- Style(s): Minimal Traditional
- Stories: 1
- Cladding: smooth stucco
- Porch: entrance porch, concrete steps, wood rail
- Door(s): single, door material unknown, metal screen
- Windows: Type 1 - single, sliding, vinyl
- Roof: hipped, composition sheets, open eaves
- Chimney: none visible
- Related Features: detached 1-car garage
- Alterations: windows replaced
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

North elevation

ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1953, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: January 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) ***Required Information**

State of California -- The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1045 CLARK ST

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1045 CLARK ST City NAPA Zip 94559

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 006293007000

*P3a. Description:

- Style(s): Minimal Traditional
- Stories: 1
- Cladding: wood clapboards
- Porch: partial width, concrete steps, wood posts, wood rail
- Door(s): single, wood, paneled
- Windows: Type 1 - single, double hung, wood; Type 2 - single, fixed, wood, multipane; Type 3 - single, sliding, vinyl
- Roof: hipped, composition shingle
- Chimney: none visible
- Related Features: detached 1-car garage, shed
- Alterations: some windows replaced
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

North elevation

ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1951, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: January 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) ***Required Information**

PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1046 CLARK ST

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1046 CLARK ST City NAPA Zip 945591449

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 006301003000

*P3a. Description:

- Style(s): Ranch, Traditional
- Stories: 1
- Cladding: wood clapboards
- Porch: entrance porch, recessed
- Door(s): single, wood, metal screen
- Windows: Type 1 - single, sliding, material unknown
- Roof: cross gable, composition shingle, open eaves, wide eaves
- Chimney: none visible
- Related Features: carport
- Alterations: windows replaced
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

South elevation

ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1952, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: January 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) *Required Information

State of California -- The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1047 CLARK ST

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1047 CLARK ST City NAPA Zip 94558

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 006293008000

*P3a. Description:

- Style(s): No style
- Stories:
- Cladding:
- Porch:
- Door(s):
- Windows:
- Roof:
- Chimney:
- Related Features:
- Alterations: Completely remodeled
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

North elevation

ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1940, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: January 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) *Required Information

State of California -- The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1100 CLARK ST

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1100 CLARK ST City NAPA Zip 945591548

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 006301009000

*P3a. Description:

- Style(s): Ranch, Contemporary
- Stories: 1
- Cladding: concrete block
- Porch: entrance porch, recessed
- Door(s): single, wood, paneled, sidelights
- Windows: Type 1 - sliding, vinyl
- Roof: hipped, composition shingle, open eaves, wide eaves
- Chimney: brick, exterior
- Related Features: attached 2-car garage
- Alterations: door replaced, windows replaced
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

South elevation

ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1960, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: January 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) ***Required Information**

State of California -- The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 7N

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1101 CLARK ST

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1101 CLARK ST City NAPA Zip 945591547

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 006294001000

*P3a. Description:

- Style(s): Ranch, Contemporary
- Stories: 1 1/2
- Cladding: wood clapboards
- Porch: entrance porch, concrete steps, wood posts
- Door(s): single, wood, sidelights
- Windows: Type 1 - grouped, casement, fixed, wood
- Roof: hipped, composition shingle, boxed eaves, wide eaves
- Chimney: brick, exterior
- Related Features: attached 1-car garage
- Alterations: none visible
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

North elevation

ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1952, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: January 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) ***Required Information**

PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 7N

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1121 CLARK ST

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1121 CLARK ST City NAPA Zip 945581245

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 006294002000

*P3a. Description:

- Style(s): Modernism, Mid-Century
- Stories: 1 1/2
- Cladding: brick
- Porch: entrance porch, concrete steps, pierced brick, iron rail
- Door(s): single, wood, metal screen
- Windows: Type 1 - sliding, aluminum
- Roof: front gable, exposed purlins, wide eaves
- Chimney: none visible
- Related Features: attached 2-car garage
- Alterations: none visible
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

North elevation

ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1960, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: January 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) ***Required Information**

State of California -- The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1069 EAST AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1069 EAST AVE City NAPA Zip 94558

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 006086007000

*P3a. Description:

- Style(s): Modernism, Mid-Century
- Stories: 1
- Cladding: wood clapboards
- Porch: none
- Door(s): single, wood, divided lights, partially glazed
- Windows: Type 1 - single, casement, steel, shutters
- Roof: flat, wide eaves
- Chimney: none visible
- Related Features: carport
- Alterations: windows replaced
- Notes: Part of a larger complex of buildings that front both East and Evans

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

East elevation

ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

c. 1940, architectural estimate

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: January 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) ***Required Information**

State of California -- The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1073 EAST AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1073 EAST AVE City NAPA Zip 94558

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 006086006000

*P3a. Description:

- Style(s): Modernism, Mid-Century
- Stories: 1
- Cladding: wood clapboards
- Porch: none
- Door(s): not visible
- Windows: Type 1 - grouped, sliding, vinyl; Type 2 - grouped, casement, wood
- Roof: flat
- Chimney: none visible
- Related Features: carport
- Alterations: some windows replaced
- Notes: Part of a larger complex of buildings that front both Evans and East

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

East elevation

ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

c. 1940, architectural estimate

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: January 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) ***Required Information**

State of California -- The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1075 EAST AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1075 EAST AVE City NAPA Zip 94559

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 006086005000

*P3a. Description:

- Style(s): Craftsman
- Stories: 1
- Cladding: wood clapboards, wood shingles
- Porch: none
- Door(s): single, wood, paneled, sidelights
- Windows: Type 1 - single, double hung, vinyl
- Roof: front gable, exposed rafter tails, open eaves
- Chimney: none visible
- Related Features: detached 1-car garage
- Alterations: completely remodeled, cladding altered, door replaced, windows replaced
- Notes: Property also has frontage on Evans

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

East elevation

ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1910, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: January 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) ***Required Information**

State of California -- The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1085 EAST AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1085 EAST AVE City NAPA Zip 945592146

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 006086001000

*P3a. Description:

- Style(s): Minimal Traditional
- Stories: 1
- Cladding: smooth stucco
- Porch: entrance porch, concrete steps, wood posts, wood rail
- Door(s): single, wood, paneled
- Windows: Type 1 - single, fixed, aluminum; Type 2 - single, double hung, vinyl
- Roof: cross gable, composition shingle, exposed rafter tails, open eaves
- Chimney: none visible
- Related Features: attached 1-car garage
- Alterations: windows replaced
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:
South and east elevations
ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1938, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: January 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) ***Required Information**

State of California -- The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1105 EAST AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1105 EAST AVE City NAPA Zip 956840244

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 006084010000

*P3a. Description:

- Style(s): Minimal Traditional
- Stories: 1
- Cladding: smooth stucco
- Porch: partial width, concrete steps, wood posts
- Door(s): single, wood, divided lights, paneled
- Windows: Type 1 - single, fixed, multipane; Type 2 - paired, double hung, vinyl, shutters; Type 3 - single, double hung, vinyl
- Roof: combination, front gable, hipped, open eaves
- Chimney: brick, interior
- Related Features: attached 1-car garage
- Alterations: some windows replaced
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

East elevation

ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1949, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: January 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) ***Required Information**

State of California -- The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1109 EAST AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1109 EAST AVE City NAPA Zip 945591525

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 006084009000

*P3a. Description:

- Style(s): Minimal Traditional
- Stories: 1
- Cladding: asbestos
- Porch: partial width, concrete steps, wood posts, wood rail
- Door(s): ; Secondary - single, wood
- Windows: Type 1 - paired, double hung, wood; Type 2 - single, sliding, aluminum; Type 3 - paired, double hung, wood, multipane
- Roof: side gable, composition shingle, open eaves
- Chimney: none visible
- Related Features:
- Alterations: cladding altered, some windows replaced
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

East elevation

ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1938, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: January 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) ***Required Information**

PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6L

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1166 EAST AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1166 EAST AVE City NAPA Zip 945592145

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 045153013000


*P3a. Description:

- Style(s): Minimal Traditional
- Stories: 1
- Cladding: smooth stucco
- Porch: partial width, concrete steps, wood posts, wood rail
- Door(s): single, wood, paneled
- Windows: Type 1 - single, fixed, wood, multipane; Type 2 - single, double hung, wood; Type 3 - single, casement, wood
- Roof: cross hipped, boxed eaves
- Chimney: none visible
- Related Features: detached 1-car garage
- Alterations: none visible
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

West elevation
ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both
1949, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.
Pier 9, The Embarcadero
San Francisco, California 94111

*P9. Date Recorded: January 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic
Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) *Required Information

State of California -- The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1176 EAST AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1176 EAST AVE City NAPA Zip 945592145

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 045153014000

*P3a. Description:

- Style(s): Minimal Traditional
- Stories: 1
- Cladding: textured stucco
- Porch: entrance porch, recessed, concrete steps, iron rail
- Door(s): single, wood, paneled
- Windows: Type 1 - paired, double hung, wood, multipane top sash, historic surround; Type 2 - single, double hung, wood, multipane top sash
- Roof: side gable, composition shingle
- Chimney: none visible
- Related Features: detached 1-car garage
- Alterations: cladding altered
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

West elevation

ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1938, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: January 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) ***Required Information**

State of California -- The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1186 EAST AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1186 EAST AVE City NAPA Zip 94901

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 045153015000

*P3a. Description:

- Style(s): Minimal Traditional
- Stories: 1
- Cladding: aluminum
- Porch: entrance porch, recessed, concrete steps
- Door(s): single, wood, wood screen
- Windows: Type 1 - single, double hung, vinyl; Type 2 - single, sliding, vinyl
- Roof: cross gable, composition sheets
- Chimney: brick, exterior
- Related Features:
- Alterations: cladding altered, windows replaced
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

West elevation

ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1935, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: January 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) ***Required Information**

PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1196 EAST AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1196 EAST AVE City NAPA Zip 945592145

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 045153001000

*P3a. Description:

- Style(s): Minimal Traditional
- Stories: 1
- Cladding: aluminum
- Porch: entrance porch, concrete steps, iron rail
- Door(s): single, wood, partially glazed
- Windows: Type 1 - paired, double hung, vinyl; Type 2 - single, double hung, vinyl
- Roof: cross gable, composition shingle
- Chimney: none visible
- Related Features:
- Alterations: cladding altered, door replaced, windows replaced
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

North elevation
ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both
1937, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.
Pier 9, The Embarcadero
San Francisco, California 94111

*P9. Date Recorded: January 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic
Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) *Required Information

PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1206 EAST AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1206 EAST AVE City NAPA Zip 94559

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 045151008000

*P3a. Description:

- Style(s): No style
- Stories:
- Cladding:
- Porch:
- Door(s):
- Windows:
- Roof:
- Chimney: none visible
- Related Features:
- Alterations: Completely remodeled
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:
West elevation
ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both
1936, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: January 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) *Required Information

PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1212 EAST AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1212 EAST AVE City NAPA Zip 94559

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 045151009000

*P3a. Description:

- Style(s): Modernism, Mid-Century
- Stories: 1
- Cladding: board and batten
- Porch: recessed, iron rail
- Door(s): not visible
- Windows: Type 1 - grouped, casement, vinyl; Type 2 - single, sliding, vinyl
- Roof: front gable, material not visible, wide eaves
- Chimney: brick, exterior
- Related Features: detached 1-car garage
- Alterations: windows replaced
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:
West and north elevations
ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both
1961, Napa City & County records

*P7. Owner and Address:
Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis
Architectural Resources Group, Inc.
Pier 9, The Embarcadero
San Francisco, California 94111

*P9. Date Recorded: January 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic
Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) *Required Information

State of California -- The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1216 EAST AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1216 EAST AVE City NAPA Zip 94558

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 045151010000

*P3a. Description:

- Style(s): Craftsman
- Stories: 1
- Cladding: wood clapboards
- Porch: entrance porch, concrete steps, wood posts, wood rail
- Door(s): wood, divided lights, fully glazed
- Windows: Type 1 - single, double hung, aluminum; Type 2 - single, fixed, material unknown
- Roof: side gable, composition shingle, exposed rafter tails, open eaves
- Chimney: none visible
- Related Features: detached 1-car garage
- Alterations: windows replaced
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:
West and south elevations
ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1945, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: January 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) ***Required Information**

PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1220 EAST AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1220 EAST AVE City NAPA Zip 94558

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 045151011000

*P3a. Description:

- Style(s): Craftsman
- Stories: 1
- Cladding: wood clapboards
- Porch: entrance porch, wood steps, wood posts, wood rail
- Door(s): single, wood, wood screen
- Windows: Type 1 - single, double hung, vinyl; Type 2 - single, fixed, vinyl
- Roof: front gable, composition shingle, exposed rafter tails, open eaves
- Chimney: brick, exterior
- Related Features: shed
- Alterations: windows replaced
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

West elevation

ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1938, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: January 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) ***Required Information**

PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1225 EAST AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1225 EAST AVE City NAPA Zip 945592032

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 045143013000

*P3a. Description:

- Style(s): Victorian, Vernacular Cottage, hip roof
- Stories: 1
- Cladding: wood clapboards
- Porch: full width, wood posts
- Door(s): single, wood, divided lights
- Windows: Type 1 - single, fixed, vinyl; Type 2 - single, sliding, vinyl; Type 3 - single, casement, wood
- Roof: hipped, composition shingle, open eaves
- Chimney: none visible
- Related Features: attached 1-car garage
- Alterations: windows replaced, garage added to side elevation
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

West elevation
ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1940, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: January 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) ***Required Information**

State of California -- The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1226 EAST AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1226 EAST AVE City NAPA Zip 945592031

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 045151012000

*P3a. Description:

- Style(s): Craftsman
- Stories: 1
- Cladding: wood clapboards
- Porch: entrance porch, stone veneer steps, wood posts, wood rail
- Door(s): single, wood, paneled
- Windows: Type 1 - single, fixed, vinyl; Type 2 - single, double hung, vinyl
- Roof: side gable, composition shingle, exposed rafter tails, open eaves
- Chimney: brick, exterior
- Related Features: detached 1-car garage
- Alterations: door replaced, windows replaced
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

West elevation

ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1935, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: January 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) ***Required Information**

PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1230 EAST AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1230 EAST AVE City NAPA Zip 945592031

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 045151001000

*P3a. Description:

- Style(s): Minimal Traditional
- Stories: 1
- Cladding: vinyl
- Porch: entrance porch, concrete steps, wood posts, wood rail
- Door(s): single, door material unknown
- Windows: Type 1 - single, fixed, aluminum; Type 2 - single, double hung, aluminum
- Roof: side gable, composition shingle
- Chimney: stucco, exterior
- Related Features: detached 1-car garage
- Alterations: cladding altered, windows replaced, lattice and awning at porch
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

West elevation
ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both
1945, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.
Pier 9, The Embarcadero
San Francisco, California 94111

*P9. Date Recorded: January 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic
Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) *Required Information

State of California -- The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1237 EAST AVE

P1. Other Identifier: _____

***P2. Location:** Not for Publication Unrestricted

***a. County** Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

***b. USGS 7.5' Quad** _____ **Date** _____ **T** _____; **R** _____; **1/4 of** _____ **1/4 of Sec** _____; **B.M.**

c. Address 1237 EAST AVE City NAPA Zip 945592032

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 045143006000

***P3a. Description:**

- Style(s): Craftsman
- Stories: 1
- Cladding: wood clapboards
- Porch: full width, concrete
- Door(s): single, wood, divided lights
- Windows: Type 1 - single, fixed, wood, multipane; Type 2 - single, sliding, aluminum; Type 3 - single, double hung, wood
- Roof: front gable, composition sheets, brackets, open eaves
- Chimney: none visible
- Related Features: shed
- Alterations: Early porch enclosure
- Notes:

***P3b. Resource Attributes:** (List attributes and codes) HP2. Single family property

***P4. Resources Present:** Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

East elevation

ARG, January 2011

***P6. Date Constructed/Age and Source:**

Historic Prehistoric Both

1930, Napa City & County records

***P7. Owner and Address:**

Not recorded

***P8. Recorded by:** K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

***P9. Date Recorded:** January 2011

***P10. Survey Type:** Intensive

***P11. Report Citation:** Alta Heights Historic

Context Statement and Survey Report

***Attachments:** NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) ***Required Information**

State of California -- The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6L

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1242 EAST AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1242 EAST AVE City NAPA Zip 945591519

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 045122006000

*P3a. Description:

- Style(s): Minimal Traditional
- Stories: 1
- Cladding: smooth stucco
- Porch: entrance porch, recessed, concrete steps, iron rail
- Door(s): single, wood, paneled, wood screen
- Windows: Type 1 - paired, double hung, wood; Type 2 - tripartite, double hung, fixed, wood
- Roof: cross hipped, composition sheets
- Chimney: stucco, exterior
- Related Features: attached 1-car garage
- Alterations: none visible
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

West elevation

ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1938, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: January 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) *Required Information

State of California -- The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1244 EAST AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1244 EAST AVE City NAPA Zip 94559

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 045122007000

*P3a. Description:

- Style(s): Minimal Traditional
- Stories: 1
- Cladding: smooth stucco
- Porch: entrance porch, brick steps, wood posts, iron rail
- Door(s): single, wood
- Windows: Type 1 - canted bay, double hung, fixed, vinyl; Type 2 - paired, double hung, vinyl
- Roof: cross gable, composition shingle, open eaves
- Chimney: stucco, exterior
- Related Features: detached 1-car garage
- Alterations: cladding altered, door replaced, windows replaced
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

West elevation
ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both
1936, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.
Pier 9, The Embarcadero
San Francisco, California 94111

*P9. Date Recorded: January 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic
Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) ***Required Information**

State of California -- The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1265 EAST AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1265 EAST AVE City NAPA Zip 945593136

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 045143005000

*P3a. Description:

- Style(s): Minimal Traditional
- Stories: 1
- Cladding: textured stucco
- Porch: entrance porch, concrete steps, wood posts, wood rail
- Door(s): single, wood, paneled, metal screen
- Windows: Type 1 - single, sliding, vinyl
- Roof: side gable, composition shingle
- Chimney: none visible
- Related Features: detached 1-car garage
- Alterations: addition to side elevation, cladding altered, door replaced, windows replaced
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

East elevation

ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1900, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: January 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) ***Required Information**

State of California -- The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6L

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1306 EAST AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1306 EAST AVE City NAPA Zip 94558

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 045122011000

*P3a. Description:

- Style(s): Minimal Traditional
- Stories: 1
- Cladding: wood clapboards
- Porch: entrance porch, concrete steps, wood battered posts, wood solid rail
- Door(s): single, wood
- Windows: Type 1 - paired, double hung, wood
- Roof: side gable, composition sheets
- Chimney: brick, exterior
- Related Features: detached 1-car garage
- Alterations: none visible
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

West elevation
ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both
1936, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.
Pier 9, The Embarcadero
San Francisco, California 94111

*P9. Date Recorded: January 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic
Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) ***Required Information**

P1. Other Identifier: _____

***P2. Location:** Not for Publication Unrestricted

***a. County** Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

***b. USGS 7.5' Quad** _____ **Date** _____ **T** _____; **R** _____; **1/4 of** _____ **1/4 of Sec** _____; _____ **B.M.**

c. Address 1322 EAST AVE City NAPA Zip 945592045

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 045122001000

***P3a. Description:**

- Style(s): Minimal Traditional
- Stories: 1
- Cladding: wood clapboards
- Porch: entrance porch, concrete steps, wood posts, wood rail
- Door(s): single, wood, partially glazed, paneled; Secondary - single, wood, paneled
- Windows: Type 1 - single, fixed, wood, multipane; Type 2 - single, double hung, wood, multipane top sash; Type 3 - single, double hung, wood
- Roof: cross gable, composition shingle
- Chimney: none visible
- Related Features: detached 2-car garage
- Alterations: none visible
- Notes:

***P3b. Resource Attributes:** (List attributes and codes) HP2. Single family property

***P4. Resources Present:** Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

North and west elevations
ARG, January 2011

***P6. Date Constructed/Age and Source:**

Historic Prehistoric Both
1938, Napa City & County records

***P7. Owner and Address:**

Not recorded

***P8. Recorded by:** K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.
Pier 9, The Embarcadero
San Francisco, California 94111

***P9. Date Recorded:** January 2011

***P10. Survey Type:** Intensive

***P11. Report Citation:** Alta Heights Historic
Context Statement and Survey Report

***Attachments:** NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) ***Required Information**

State of California -- The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6L

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1401-1405 EAST AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1401-1405 EAST AVE City NAPA Zip 94595

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 045114009000

*P3a. Description:

- Style(s): Minimal Traditional
- Stories: 1
- Cladding: wood clapboards
- Porch: entrance porch, wood brackets
- Door(s): single, wood, paneled, metal screen; Secondary - single, wood, paneled, metal screen
- Windows: Type 1 - tripartite, double hung, fixed, wood; Type 2 - single, double hung, wood
- Roof: cross gable, composition shingle
- Chimney: none visible
- Related Features: attached 2-car garage
- Alterations: none visible
- Notes: Duplex

*P3b. Resource Attributes: (List attributes and codes) HP3. Multiple family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

East elevation

ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

c. 1940, architectural estimate

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: January 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) ***Required Information**

PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1406 EAST AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1406 EAST AVE City NAPA Zip 945094211

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 045121011000

*P3a. Description:

- Style(s): Minimal Traditional
- Stories: 1
- Cladding: textured stucco
- Porch: entrance porch, recessed, concrete steps
- Door(s): single, wood, metal screen
- Windows: Type 1 - tripartite, double hung, fixed, wood; Type 2 - single, double hung, wood
- Roof: cross gable, composition sheets
- Chimney: none visible
- Related Features: detached 1-car garage
- Alterations: none visible
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

West elevation
ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both
1942, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.
Pier 9, The Embarcadero
San Francisco, California 94111

*P9. Date Recorded: January 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic
Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) *Required Information

State of California -- The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1407 EAST AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1407 EAST AVE City NAPA Zip 94559

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 045114008000

***P3a. Description:**

- Style(s): Minimal Traditional
- Stories: 1
- Cladding: vinyl
- Porch: recessed, concrete steps
- Door(s): single, door material unknown, metal screen
- Windows: Type 1 - tripartite, casement, fixed, vinyl; Type 2 - single, sliding, vinyl; Type 3 - single, double hung, vinyl
- Roof: cross gable, composition shingle
- Chimney: none visible
- Related Features: detached 1-car garage
- Alterations: cladding altered, windows replaced
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

East elevation

ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1951, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: January 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) ***Required Information**

State of California -- The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1408 EAST AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1408 EAST AVE City NAPA Zip 945591546

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 045121012000

*P3a. Description:

- Style(s): Minimal Traditional
- Stories: 1
- Cladding: smooth stucco, wood clapboards
- Porch: entrance porch, concrete steps, iron posts
- Door(s): single, wood, wood screen
- Windows: Type 1 - single, sliding, vinyl; Type 2 - single, double hung, vinyl
- Roof: hipped, exposed rafter tails, open eaves
- Chimney: none visible
- Related Features: detached 1-car garage
- Alterations: windows replaced
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:
West elevation
ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1948, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: January 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) ***Required Information**

State of California -- The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1409 EAST AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1409 EAST AVE City NAPA Zip 945591545

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 045114007000

*P3a. Description:

- Style(s): Minimal Traditional
- Stories: 1
- Cladding: fieldstone, vinyl
- Porch: entrance porch, concrete steps, iron rail
- Door(s): single, wood, paneled, metal screen
- Windows: Type 1 - tripartite, double hung, fixed, vinyl; Type 2 - single, double hung, vinyl; Type 3 - single, double hung, wood, multipane
- Roof: side gable, composition sheets
- Chimney: none visible
- Related Features: attached 1-car garage
- Alterations: cladding altered, some windows replaced, garage door replaced
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

East elevation

ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1940, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: January 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) ***Required Information**

State of California -- The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1410 EAST AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1410 EAST AVE City NAPA Zip 94559

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 045121013000

*P3a. Description:

- Style(s): Minimal Traditional
- Stories: 1
- Cladding: brick, wood clapboards, wood vertical boards
- Porch: entrance porch, concrete steps, wood posts
- Door(s): single, door material unknown, metal screen
- Windows: Type 1 - paired, double hung, vinyl; Type 2 - single, double hung, vinyl
- Roof: cross gable, composition sheets
- Chimney: none visible
- Related Features: attached 1-car garage
- Alterations: windows replaced, garage door replaced
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

West elevation

ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1942, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: January 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) ***Required Information**

PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1412 EAST AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1412 EAST AVE City NAPA Zip 945583114

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 045121014000

*P3a. Description:

- Style(s): Minimal Traditional
- Stories: 1
- Cladding: smooth stucco
- Porch: entrance porch, recessed, concrete steps, stucco solid rail
- Door(s): single, wood, paneled, wood screen
- Windows: Type 1 - paired, double hung, vinyl; Type 2 - paired, double hung, wood, multipane top sash
- Roof: cross hipped, composition shingle, exposed rafter tails, open eaves
- Chimney: none visible
- Related Features: detached 1-car garage
- Alterations: some windows replaced
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

West elevation
ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both
1941, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.
Pier 9, The Embarcadero
San Francisco, California 94111

*P9. Date Recorded: January 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic
Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) *Required Information