

PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1027 SUMMIT AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1027 SUMMIT AVE City NAPA Zip 945591407

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 045062001000

*P3a. Description:

- Style(s): Minimal Traditional
- Stories: 1
- Cladding: wood clapboards
- Porch: entrance porch, partial width, wood steps, wood posts, wood rail, solid rail
- Door(s): single, wood
- Windows: Type 1 - single, fixed, wood, multipane; Type 2 - single, sliding, vinyl, multipane
- Roof: cross gable, composition shingle, open eaves
- Chimney: none visible
- Related Features: attached 1-car garage
- Alterations: some window openings resized, windows replaced, porch altered, deck added to side elevation
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

North elevation

ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1936, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: April 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) ***Required Information**

State of California -- The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1028 SUMMIT AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1028 SUMMIT AVE City NAPA Zip 945591408

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) _____ APN 045051012000

*P3a. Description:

- Style(s): No style
- Stories: 3
- Cladding: smooth stucco, wood clapboards
- Porch: wraparound, wood steps, wood posts, wood rail
- Door(s): single, wood, divided lights, partially glazed, paneled, wood screen; Secondary - single, wood, paneled, wood screen
- Windows: Type 1 - paired, double hung, vinyl; Type 2 - single, double hung, aluminum; Type 3 - single, fixed, material unknown
- Roof: combination, cross gable, hipped, clay tile, open eaves
- Chimney: brick, exterior
- Related Features:
- Alterations: completely remodeled, addition to primary façade, awnings incompatible, windows replaced, Declan added on 2 facades. Incompatible roof material.
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

South elevation

ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1950, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: April 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):

DPR 523A (1/95)

*Required Information

State of California -- The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6L

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1029 SUMMIT AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1029 SUMMIT AVE City NAPA Zip 94559

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 045072001000

*P3a. Description:

- Style(s): Modernism, Mid-Century / Ranch, Minimal
- Stories: 1
- Cladding: board and batten, smooth stucco
- Porch: entrance porch, brick steps
- Door(s): single, wood; Secondary - single, wood
- Windows: Type 1 - single, sliding, vinyl
- Roof: flat, material not visible, boxed eaves
- Chimney: brick, exterior
- Related Features: carport
- Alterations: none visible
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

North elevation

ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1952, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: April 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) *Required Information

PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1033 SUMMIT AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1033 SUMMIT AVE City NAPA Zip 94558

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 045071001000

*P3a. Description:

- Style(s): Ranch, Minimal
- Stories: 1
- Cladding: wood lap
- Porch: partial width, concrete steps, pierced iron rail
- Door(s): single, wood, paneled
- Windows: Type 1 - tripartite, fixed, vinyl, double hung, vinyl; Type 2 - single, double hung, vinyl
- Roof: side gable, composition shingle, open eaves
- Chimney: brick, exterior
- Related Features:
- Alterations: some windows replaced, appears that an attached single car garage was converted to inhabitable space.
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

North elevation

ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1952, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: April 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) *Required Information

State of California -- The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1034 SUMMIT AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1034 SUMMIT AVE City NAPA Zip 945591406

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 045053008000

*P3a. Description:

- Style(s): American Colonial Revival
- Stories: 2
- Cladding: vinyl, wood clapboards
- Porch: entrance porch, wood posts
- Door(s): single, wood, partially glazed, paneled
- Windows: Type 1 - tripartite, double hung, vinyl, fixed, vinyl; Type 2 - single, double hung, vinyl
- Roof: hipped, open eaves
- Chimney: brick, exterior
- Related Features: side porch and rear addition (possible attached garage)
- Alterations: addition to rear elevation, cladding altered, door replaced
- Notes: Gabled hood on entrance porch

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

South elevation

ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1950, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: April 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) ***Required Information**

PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1036 SUMMIT AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1036 SUMMIT AVE City NAPA Zip 945591406

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 045053007000

*P3a. Description:

- Style(s): Minimal Traditional / Ranch
- Stories: 1
- Cladding: fieldstone, wood lap
- Porch: partial width, concrete steps, wood posts
- Door(s): single, wood, partially glazed
- Windows: Type 1 - tripartite, fixed, vinyl, double hung, vinyl
- Roof: cross gable, composition shingle, boxed eaves, open eaves
- Chimney: stone, exterior
- Related Features: attached 2-car garage
- Alterations: completely remodeled
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:
South elevation
ARG, January 2011

*P6. Date Constructed/Age and Source:
 Historic Prehistoric Both
1953, Napa City & County records

*P7. Owner and Address:
Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis
Architectural Resources Group, Inc.
Pier 9, The Embarcadero
San Francisco, California 94111

*P9. Date Recorded: April 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic
Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) *Required Information

PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1042 SUMMIT AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1042 SUMMIT AVE City NAPA Zip 945591406

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 045053006000

*P3a. Description:

- Style(s): American Colonial Revival
- Stories: 1
- Cladding: wood lap, wood vertical boards
- Porch: partial width, brick steps, wood posts
- Door(s): single, wood, wood screen
- Windows: Type 1 - single, double hung, vinyl, shutters; Type 2 - tripartite, fixed, vinyl, double hung, vinyl
- Roof: side gable, composition shingle, open eaves
- Chimney: none visible
- Related Features: attached 1-car garage
- Alterations: some windows replaced
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

South elevation
ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both
1950, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.
Pier 9, The Embarcadero
San Francisco, California 94111

*P9. Date Recorded: April 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic
Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) *Required Information

PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1050 SUMMIT AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1050 SUMMIT AVE City NAPA Zip 945591406

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 045053005000

*P3a. Description:

- Style(s): No style
- Stories: 1
- Cladding: permastone, vinyl
- Porch: partial width, concrete steps
- Door(s): single, wood
- Windows: Type 1 - single, sliding, aluminum
- Roof: side gable, composition shingle, open eaves
- Chimney: brick, exterior
- Related Features: attached 1-car garage
- Alterations: cladding altered, windows replaced
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

South elevation
ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both
1952, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.
Pier 9, The Embarcadero
San Francisco, California 94111

*P9. Date Recorded: April 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic
Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) *Required Information

State of California -- The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1067 SUMMIT AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1067 SUMMIT AVE City NAPA Zip 94590

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 045073002000

*P3a. Description:

- Style(s): Spanish Colonial Revival
- Stories: 1
- Cladding: textured stucco
- Porch: entrance porch, brick steps, stucco arches
- Door(s): single, wood, paneled
- Windows: Type 1 - single, double hung, aluminum; Type 2 - grouped, tripartite, fixed, aluminum, double hung, aluminum
- Roof: side gable, composition shinglecomposition sheetsflat
- Chimney: none visible
- Related Features: attached 1-car garage
- Alterations: some windows replaced, roof likely originally clay tile, possible porch infill or other modification at northern part of main façade.
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

North elevation

ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1940, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: April 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) ***Required Information**

State of California -- The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1069 SUMMIT AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1069 SUMMIT AVE City NAPA Zip 945591404

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 045073003000

*P3a. Description:

- Style(s): Craftsman
- Stories: 1
- Cladding: smooth stucco
- Porch: entrance porch, concrete steps, wood brackets
- Door(s): not visible, single, metal screen
- Windows: Type 1 - single, double hung, wood, shutters
- Roof: front gable, composition shingle, brackets, exposed purlins, open eaves
- Chimney: none visible
- Related Features: detached 1-car garage
- Alterations: completely remodeled, cladding altered, door opening remodeled, porch enclosed
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

North elevation

ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1938, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: April 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) ***Required Information**

PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1071 SUMMIT AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1071 SUMMIT AVE City NAPA Zip 945591404

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 045073004000

*P3a. Description:

- Style(s): Minimal Traditional
- Stories: 1
- Cladding: wood lap
- Porch: entrance porch, recessed, brick steps
- Door(s): single, door material unknown, wood screen; Secondary - none, single, wood, partially glazed
- Windows: Type 1 - single, fixed, vinyl, shutters; Type 2 - single, double hung, vinyl, shutters
- Roof: combination, cross hipped, front gable, composition shingle, exposed rafter tails, open eaves
- Chimney: none visible
- Related Features: detached 1-car garage
- Alterations: some windows replaced
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:
North elevation
ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both
1950, Napa City & County records

*P7. Owner and Address:
Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis
Architectural Resources Group, Inc.
Pier 9, The Embarcadero
San Francisco, California 94111

*P9. Date Recorded: April 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic
Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) *Required Information

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1074 SUMMIT AVE City NAPA Zip 945591403

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 045054007000

*P3a. Description:

- Style(s): No style
- Stories: 1 1/2
- Cladding: wood vertical boards
- Porch: full width, brick steps, wood posts wood rail
- Door(s): single, wood, partially glazed, paneled
- Windows: Type 1 - single, double hung, aluminum
- Roof: hipped, composition shingle
- Chimney: none visible
- Related Features: detached 1-car garage
- Alterations:
- Notes: House set back from street with mature landscaping blocking view of building

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

South elevation

ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1950, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: April 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) ***Required Information**

State of California -- The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1075 SUMMIT AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1075 SUMMIT AVE City NAPA Zip 945591404

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 045073005000

*P3a. Description:

- Style(s): Minimal Traditional
- Stories: 1
- Cladding: wood clapboards
- Porch: recessed, concrete steps, wood posts
- Door(s): not visible, door material unknown, wood screen
- Windows: Type 1 - single, sliding, aluminum, shutters; Type 2 - tripartite, double hung, aluminum, fixed
- Roof: cross gable, composition shingle, boxed eaves
- Chimney: brick, exterior
- Related Features: attached 1-car garage
- Alterations: none visible
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

North elevation
ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both
1954, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.
Pier 9, The Embarcadero
San Francisco, California 94111

*P9. Date Recorded: April 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic
Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) ***Required Information**

PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1077 SUMMIT AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1077 SUMMIT AVE City NAPA Zip 945591404

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 045073006000

*P3a. Description:

- Style(s): Ranch, Contemporary
- Stories: 2
- Cladding: smooth stucco, wood clapboards
- Porch: none visible
- Door(s): not visible, door material unknown
- Windows: Type 1 - tripartite, sliding, aluminum
- Roof: front gable, composition shingle
- Chimney: brick, exterior
- Related Features: attached 2-car garage
- Alterations:
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:
North elevation
ARG, January 2011

*P6. Date Constructed/Age and Source:
 Historic Prehistoric Both
1964, Napa City & County records

*P7. Owner and Address:
Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis
Architectural Resources Group, Inc.
Pier 9, The Embarcadero
San Francisco, California 94111

*P9. Date Recorded: April 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic
Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) *Required Information

PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6L

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1080 SUMMIT AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1080 SUMMIT AVE City NAPA Zip 94559

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 045054008000

*P3a. Description:

- Style(s): Ranch, Minimal
- Stories: 1
- Cladding: concrete block
- Porch: entrance porch, concrete steps, wood posts wood rail
- Door(s): single, security door, door material unknown
- Windows: Type 1 - single, casement, steel, multipane
- Roof: hipped, composition shingle, wide eaves
- Chimney: stone, exterior
- Related Features:
- Alterations: security door added
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:
South elevation
ARG, January 2011

*P6. Date Constructed/Age and Source:
 Historic Prehistoric Both
1954, Napa City & County records

*P7. Owner and Address:
Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis
Architectural Resources Group, Inc.
Pier 9, The Embarcadero
San Francisco, California 94111

*P9. Date Recorded: April 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic
Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) *Required Information

PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6L

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1090 SUMMIT AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1090 SUMMIT AVE City NAPA Zip 945591403

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 006292005000

*P3a. Description:

- Style(s): Modernism, Mid-Century
- Stories: 1
- Cladding: smooth stucco
- Porch: entrance porch, concrete steps, wood posts, pierced iron rail
- Door(s): single, door material unknown, metal screen
- Windows: Type 1 - tripartite, fixed, wood, double hung; Type 2 - grouped, double hung, wood; Type 3 - single, double hung, wood
- Roof: flat, material not visible, open eaves
- Chimney: stucco, exterior
- Related Features:
- Alterations: security door added, porch rails altered, disabled access ramp added to front entry
- Notes: Basement

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

East elevation
ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both
1955, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.
Pier 9, The Embarcadero
San Francisco, California 94111

*P9. Date Recorded: April 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic
Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) ***Required Information**

PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1091 SUMMIT AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1091 SUMMIT AVE City NAPA Zip 945591404

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) _____ APN 045073007000

*P3a. Description:

- Style(s): Minimal Traditional
- Stories: 1
- Cladding: wood clapboards
- Porch: entrance porch, concrete steps, pierced iron rail
- Door(s): single, wood, partially glazed, paneled
- Windows: Type 1 - single, double hung, vinyl, shutters; Type 2 - paired, double hung, vinyl, shutters; Type 3 - tripartite, casement, vinyl, fixed, vinyl, shutters
- Roof: cross gable, composition shingle, exposed purlins
- Chimney: brick, exterior
- Related Features: carport
- Alterations: windows replaced
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

East elevation

ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1952, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: April 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):

PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1403 VALE AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1403 VALE AVE City NAPA Zip 94558

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 045112009000

*P3a. Description:

- Style(s): Ranch, Minimal
- Stories: 1
- Cladding: smooth stucco
- Porch: entrance porch, partial width, concrete steps, wood posts
- Door(s): single, wood, divided lights, paneled; Secondary - single, wood
- Windows: Type 1 - single, sliding, vinyl
- Roof: side gable, composition shingle, open eaves
- Chimney: stucco, exterior
- Related Features: attached 2-car garage
- Alterations: door replaced, some windows replaced, some window openings resized
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

East elevation

ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1957, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: April 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) *Required Information

State of California -- The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1407 VALE AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1407 VALE AVE City NAPA Zip 94559

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 045112008000

***P3a. Description:**

- Style(s): Minimal Traditional
- Stories: 1
- Cladding: smooth stucco
- Porch: partial width, concrete steps, wood posts
- Door(s): single, security door, door material unknown
- Windows: Type 1 - paired, double hung, vinyl; Type 2 - single, double hung, vinyl
- Roof: front gable, material not visible, open eaves
- Chimney: none visible
- Related Features: detached 2-car garage
- Alterations: some windows replaced
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

East elevation

ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1940, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: April 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) ***Required Information**

State of California -- The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1408 VALE AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1408 VALE AVE City NAPA Zip 945591504

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 045113013000

*P3a. Description:

- Style(s): Minimal Traditional
- Stories: 1
- Cladding: smooth stucco
- Porch: entrance porch, concrete steps, pierced iron rail
- Door(s): single, security door, door material unknown
- Windows: Type 1 - grouped, casement, vinyl
- Roof: cross hipped, composition shingle
- Chimney: brick, exterior
- Related Features: detached 1-car garage
- Alterations: awnings incompatible, security door added, porch enclosed
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

West elevation

ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1940, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: April 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) ***Required Information**

PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1410 VALE AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1410 VALE AVE City NAPA Zip 945591504

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 045113014000

*P3a. Description:

- Style(s): Minimal Traditional
- Stories: 1
- Cladding: smooth stucco
- Porch: full width, wood steps, wood posts
- Door(s): single, wood, paneled, metal screen
- Windows: Type 1 - single, double hung, wood
- Roof: side gable, composition shingle
- Chimney: brick, exterior
- Related Features:
- Alterations: none visible
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:
West elevation
ARG, January 2011

*P6. Date Constructed/Age and Source:
 Historic Prehistoric Both
1940, Napa City & County records

*P7. Owner and Address:
Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis
Architectural Resources Group, Inc.
Pier 9, The Embarcadero
San Francisco, California 94111

*P9. Date Recorded: April 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic
Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) *Required Information

State of California -- The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1411 VALE AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1411 VALE AVE City NAPA Zip 945591503

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 045112007000


*P3a. Description:

- Style(s): Minimal Traditional
- Stories: 1
- Cladding: smooth stucco
- Porch: partial width, concrete steps, wood posts, pierced iron rail
- Door(s): single, door material unknown
- Windows: Type 1 - single, double hung, aluminum
- Roof: cross gable, composition shingle
- Chimney:
- Related Features: detached 1-car garage
- Alterations: some windows replaced, some window openings resized, porch rails altered
- Notes: Metal pipe chimney

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

East elevation

ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1946, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: April 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) ***Required Information**

State of California -- The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1413 VALE AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1413 VALE AVE City NAPA Zip 94558

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 045112006000

***P3a. Description:**

- Style(s): Minimal Traditional
- Stories: 1
- Cladding: wood lap
- Porch: entrance porch, brick steps, wood posts, wood rail
- Door(s): single, security door, door material unknown
- Windows: Type 1 - canted bay, casement, vinyl, fixed, vinyl; Type 2 - single, fixed, vinyl; Type 3 - single, double hung, material unknown
- Roof: cross gable, composition shingle, open eaves
- Chimney: stucco, exterior
- Related Features: detached 1-car garage
- Alterations: security door added, some windows replaced, some window openings resized
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

East elevation

ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1940, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: April 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) ***Required Information**

PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1414 VALE AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1414 VALE AVE City NAPA Zip 945591504

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 045113015000

*P3a. Description:

- Style(s): Minimal Traditional
- Stories: 1
- Cladding: wood lap
- Porch: partial width, recessed, stone steps, wood posts
- Door(s): single, door material unknown, metal screen
- Windows: Type 1 - single, double hung, vinyl
- Roof: combination, hipped, side gable, composition shingle, open eaves
- Chimney: brick, exterior
- Related Features: detached 1-car garage
- Alterations: windows replaced
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

West elevation
ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1940, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: April 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) *Required Information

PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1417 VALE AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1417 VALE AVE City NAPA Zip 94558

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 045112005000

*P3a. Description:

- Style(s): Minimal Traditional
- Stories: 1
- Cladding: permastone, wood lap
- Porch: entrance porch, recessed, concrete steps
- Door(s): single, wood, divided lights, partially glazed, paneled
- Windows: Type 1 - single, double hung, wood, multipane
- Roof: cross hipped, composition sheets, boxed eaves
- Chimney: stone, exterior
- Related Features: detached 1-car garage
- Alterations: cladding altered
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

East elevation

ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

c. 1941, architectural estimate

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: April 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) *Required Information

PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1418 VALE AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1418 VALE AVE City NAPA Zip 945592334

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 045113016000

*P3a. Description:

- Style(s): Minimal Traditional
- Stories: 1
- Cladding: wood lap
- Porch: entrance porch, concrete steps, wood posts
- Door(s): single, wood, partially glazed, paneled
- Windows: Type 1 - single, double hung, vinyl
- Roof: side gable, composition shingle
- Chimney: none visible
- Related Features: detached 2-car garage
- Alterations: some window openings resized, windows replaced
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

West elevation
ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both
1940, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.
Pier 9, The Embarcadero
San Francisco, California 94111

*P9. Date Recorded: April 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic
Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) *Required Information

State of California -- The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1431 VALE AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1431 VALE AVE City NAPA Zip 945591503

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 045112004000

*P3a. Description:

- Style(s): Ranch, Custom
- Stories: 1
- Cladding: smooth stucco
- Porch: entrance porch, concrete steps, wood columns
- Door(s): single, partially glazed
- Windows: Type 1 - single, double hung, vinyl; Type 2 - grouped, double hung, vinyl
- Roof: cross hipped, composition shingle, boxed eaves
- Chimney: stucco, exterior
- Related Features: attached 2-car garage
- Alterations: completely remodeled
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

East elevation

ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1953, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: April 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) ***Required Information**

State of California -- The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1402 VISTA AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1402 VISTA AVE City NAPA Zip 945591502

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 045112017000

*P3a. Description:

- Style(s): Minimal Traditional
- Stories: 1
- Cladding: brick, smooth stucco
- Porch: entrance porch, recessed, concrete steps, pierced iron rail
- Door(s): single, wood, partially glazed, paneled
- Windows: Type 1 - single, sliding, vinyl
- Roof: cross hipped, composition shingle, intersecting gable at ridgeline, boxed eaves
- Chimney: brick, exterior
- Related Features:
- Alterations: door replaced, windows replaced
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

West elevation

ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1963, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: April 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) ***Required Information**

State of California -- The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1404 VISTA AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1404 VISTA AVE City NAPA Zip 94559

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 045112011000

*P3a. Description:

- Style(s): Minimal Traditional
- Stories: 1
- Cladding: wood lap
- Porch: partial width, concrete steps, wood posts, wood rail
- Door(s): single, door material unknown, metal screen; Secondary - not visible
- Windows: Type 1 - paired, double hung, vinyl; Type 2 - single, double hung, vinyl
- Roof: front gable, composition shingle, vergeboards, open eaves
- Chimney: none visible
- Related Features: detached 1-car garage
- Alterations: windows replaced, porch added along side elevation
- Notes: Second porch along entire side elevation. Materials identical to front, partial width porch.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

West elevation

ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1951, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: April 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) ***Required Information**

PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1408 VISTA AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1408 VISTA AVE City NAPA Zip 945591502

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 045112013000

*P3a. Description:

- Style(s): Minimal Traditional
- Stories: 1
- Cladding: wood clapboards
- Porch: partial width, concrete steps, wood posts, wood rail
- Door(s): single, door material unknown, metal screen
- Windows: Type 1 - single, fixed, vinyl; Type 2 - paired, double hung, vinyl
- Roof: cross gable, composition shingle, open eaves
- Chimney: none visible
- Related Features: detached 2-car garage
- Alterations: awnings incompatible, some window openings resized, windows replaced, porch rails altered
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

West elevation

ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1950, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: April 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) *Required Information

State of California -- The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1409 VISTA AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1409 VISTA AVE City NAPA Zip 945583810

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 045111008000

*P3a. Description:

- Style(s): Minimal Traditional
- Stories: 1
- Cladding: wood lap
- Porch: partial width, recessed, wood posts, pierced iron rail
- Door(s): not visible
- Windows: Type 1 - single, sliding, aluminum
- Roof: side gable, composition sheets, open eaves
- Chimney: brick, exterior
- Related Features:
- Alterations: windows replaced
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

East elevation

ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1940, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: April 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) ***Required Information**

State of California -- The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1410 VISTA AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1410 VISTA AVE City NAPA Zip 945591502

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 045112014000

*P3a. Description:

- Style(s): Minimal Traditional
- Stories: 1
- Cladding: wood clapboards
- Porch: partial width, concrete steps, wood spindles, wood solid rail
- Door(s): single, wood, paneled
- Windows: Type 1 - tripartite, double hung, wood, fixed, wood; Type 2 - single, double hung, wood
- Roof: front gable, composition shingle, open eaves
- Chimney: none visible
- Related Features: detached 2-car garage
- Alterations: some windows replaced, porch altered
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

West elevation

ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1938, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: April 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) ***Required Information**

PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1414 VISTA AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1414 VISTA AVE City NAPA Zip 949495306

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 045112015000

*P3a. Description:

- Style(s): Minimal Traditional / Craftsman
- Stories: 1
- Cladding: wood clapboards
- Porch: partial width, concrete steps, wood posts, pierced iron rail
- Door(s): single, wood, divided lights, fully glazed, metal screen
- Windows: Type 1 - paired, double hung, aluminum; Type 2 - single, double hung, aluminum
- Roof: jerkinhead, composition shingle, open eaves
- Chimney: none visible
- Related Features: detached 1-car garage
- Alterations: awnings incompatible, windows replaced, porch rails altered, Front porch added
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

West elevation
ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1936, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: April 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) *Required Information

State of California -- The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1415 VISTA AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1415 VISTA AVE City NAPA Zip 949495306

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 045111006000

*P3a. Description:

- Style(s): Minimal Traditional
- Stories: 1
- Cladding: wood clapboards, wood vertical boards
- Porch: partial width, concrete steps, wood posts
- Door(s): single, wood, metal screen
- Windows: Type 1 - single, fixed, vinyl; Type 2 - paired, double hung, vinyl; Type 3 - single, double hung, vinyl
- Roof: cross gable, composition shingle
- Chimney: wood, exterior
- Related Features: detached 2-car garage
- Alterations: windows replaced
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

East elevation
ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both
1940, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.
Pier 9, The Embarcadero
San Francisco, California 94111

*P9. Date Recorded: April 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic
Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) ***Required Information**

State of California -- The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1417 VISTA AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1417 VISTA AVE City NAPA Zip 945591501

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 045111005000

*P3a. Description:

- Style(s): Minimal Traditional
- Stories: 1
- Cladding: wood clapboards
- Porch: partial width, concrete steps, wood posts
- Door(s): single, wood, metal screen
- Windows: Type 1 - single, fixed, vinyl, shutters; Type 2 - paired, casement, material unknown, shutters
- Roof: cross hipped, composition shingle, open eaves
- Chimney: brick, exterior
- Related Features: detached 2-car garage
- Alterations: awnings incompatible, some windows replaced
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

East elevation
ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1940, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: April 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) ***Required Information**

State of California -- The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1418 VISTA AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1418 VISTA AVE City NAPA Zip 949495306

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 045112016000

*P3a. Description:

- Style(s): Minimal Traditional
- Stories: 1
- Cladding: smooth stucco
- Porch: entrance porch, concrete steps
- Door(s): single, wood, paneled, metal screen
- Windows: Type 1 - paired, sliding, vinyl; Type 2 - single, fixed, vinyl, shutters
- Roof: cross gable, composition shingle, open eaves
- Chimney: none visible
- Related Features: detached 2-car garage
- Alterations: awnings incompatible, windows replaced
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

West elevation

ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1950, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: April 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) ***Required Information**

State of California -- The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1422 VISTA AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1422 VISTA AVE City NAPA Zip 94558

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 045112001000

*P3a. Description:

- Style(s): Minimal Traditional
- Stories: 1
- Cladding: brick, smooth stucco
- Porch: entrance porch, brick steps, wood posts, iron rail
- Door(s): single, door material unknown, metal screen
- Windows: Type 1 - canted bay, double hung, wood, multipane; Type 2 - grouped, double hung, wood, multipane; Type 3 - single, double hung, wood, multipane
- Roof: cross gable, composition sheets, open eaves
- Chimney: brick, exterior
- Related Features:
- Alterations: perimeter fence added
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

West elevation

ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1940, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: April 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):

DPR 523A (1/95)

*Required Information

PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1423 VISTA AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1423 VISTA AVE City NAPA Zip 94559

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 045111004000

*P3a. Description:

- Style(s): Minimal Traditional
- Stories: 2
- Cladding:
- Porch: partial width, wood steps, wood posts, wood rail
- Door(s): single, door material unknown, metal screen
- Windows: Type 1 - single, double hung, vinyl; Type 2 - paired, double hung, vinyl; Type 3 - tripartite, double hung, vinyl
- Roof: side gable, composition shingle, open eaves
- Chimney: none visible
- Related Features: attached 2-car garage
- Alterations: addition to side elevation, security door added, windows replaced, porch rails altered, perimeter fence added
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

East and north elevations
ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1940, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: April 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) *Required Information

PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1109-1111 WILLOW AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1109-1111 WILLOW AVE City NAPA Zip 945589596

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 006081021000

*P3a. Description:

- Style(s): Ranch, Minimal
- Stories: 1
- Cladding: smooth stucco
- Porch: none
- Door(s): single, wood, partially glazed; Secondary - single, door material unknown, metal screen
- Windows: Type 1 - single, sliding, aluminum
- Roof: hipped, composition shingle
- Chimney: none visible
- Related Features: attached 2-car garage
- Alterations: windows replaced
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP3. Multiple family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:
South and west elevations
ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both
1957, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: January 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) *Required Information

PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1115 WILLOW AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1115 WILLOW AVE City NAPA Zip 945592101

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 006081011000

*P3a. Description:

- Style(s): Victorian, Vernacular Cottage, hip roof
- Stories: 1
- Cladding: asbestos
- Porch: partial width, wood steps, wood posts, wood rail
- Door(s): single, wood, paneled, metal screen
- Windows: Type 1 - single, double hung, aluminum
- Roof: cross hipped, brackets, exposed rafter tails, open eaves
- Chimney: none visible
- Related Features:
- Alterations: cladding altered, some window openings resized, windows replaced
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

East elevation

ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1905, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: January 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) *Required Information

PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 7N

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1127 WILLOW AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1127 WILLOW AVE City NAPA Zip 94559

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 006081010000

*P3a. Description:

- Style(s): Craftsman
- Stories: 1
- Cladding: wood clapboards
- Porch: full width, wood posts
- Door(s): single, wood
- Windows: Type 1 - tripartite, double hung, fixed, wood
- Roof: front gable, material not visible, brackets
- Chimney: stone, exterior
- Related Features:
- Alterations: none visible
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

East elevation

ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1923, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: January 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) *Required Information

State of California -- The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1134 WILLOW AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1134 WILLOW AVE City NAPA Zip 945592102

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 006082009000

*P3a. Description:

- Style(s): Craftsman
- Stories: 2 1/2
- Cladding: wood shingles
- Porch: full width, wood steps, wood rail
- Door(s): single, wood, divided lights, fully glazed, wood screen; Secondary - double, metal, divided lights, fully glazed, wood screen
- Windows: Type 1 - tripartite, double hung, wood, multipane top sash; Type 2 - canted bay, double hung, wood, multipane top sash
- Roof: combination, composition shingle, brackets, open eaves
- Chimney: brick, exterior
- Related Features: detached 1-car garage
- Alterations: second story added 1996, per City permit
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

West elevation
ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both
1926, Napa City & County records

*P7. Owner and Address:

Not recorded
K. Horak/A. Lyons/M. Davis
Architectural Resources Group, Inc.
Pier 9, The Embarcadero
San Francisco, California 94111

*P9. Date Recorded: January 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic
Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) ***Required Information**

State of California -- The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1139 WILLOW AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1139 WILLOW AVE City NAPA Zip 94559

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 006081009000

*P3a. Description:

- Style(s): Ranch, Minimal
- Stories: 1
- Cladding: brick, smooth stucco
- Porch: full width, wood posts
- Door(s): single, wood, divided lights, partially glazed
- Windows: Type 1 - single, sliding, aluminum
- Roof: hipped, built up, open eaves
- Chimney: brick, exterior
- Related Features: detached 1-car garage, porte cochere
- Alterations: windows replaced
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

East elevation

ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1957, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: January 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) ***Required Information**

PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 7N

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1144 WILLOW AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1144 WILLOW AVE City NAPA Zip 945592102

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 006082010000

*P3a. Description:

- Style(s): Craftsman
- Stories: 1
- Cladding: wood shingles
- Porch: partial width, wood steps, wood battered posts, wood rail
- Door(s): single, wood, divided lights, partially glazed, wood screen
- Windows: Type 1 - tripartite, double hung, wood, historic surround; Type 2 - grouped, casement, wood, multipane
- Roof: pyramidal hipped, composition shingle, open eaves
- Chimney: none visible
- Related Features: detached 1-car garage
- Alterations: none visible
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

West elevation
ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both
1910, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.
Pier 9, The Embarcadero
San Francisco, California 94111

*P9. Date Recorded: January 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic
Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) *Required Information

PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5S3
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1151 WILLOW AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1151 WILLOW AVE City NAPA Zip 94558

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 006081008000

*P3a. Description:

- Style(s): American Colonial Revival
- Stories: 2
- Cladding: wood clapboards
- Porch: partial width, concrete steps, wood columns, wood solid rail
- Door(s): single, wood, partially glazed; Secondary - single, wood, divided lights, fully glazed
- Windows: Type 1 - single, double hung, wood, historic surround; Type 2 - paired, double hung, wood, historic surround
- Roof: combination, composition shingle, boxed eaves
- Chimney: none visible
- Related Features: detached 1-car garage
- Alterations: none visible
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

East elevation
ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both
1898, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.
Pier 9, The Embarcadero
San Francisco, California 94111

*P9. Date Recorded: January 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic
Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) *Required Information

PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 7N

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1165 WILLOW AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1165 WILLOW AVE City NAPA Zip 945592101

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 006081007000

*P3a. Description:

- Style(s): American Colonial Revival
- Stories: 2
- Cladding: wood clapboards
- Porch: partial width, concrete steps, wood posts, wood solid rail
- Door(s): single, wood, divided lights, wood screen
- Windows: Type 1 - single, double hung, vinyl; Type 2 - paired, double hung, vinyl
- Roof: cross gable, composition shingle, open eaves
- Chimney: wood, exterior
- Related Features: detached 1-car garage
- Alterations: windows replaced
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

East elevation

ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1922, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: January 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) *Required Information

PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 7N

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1170 WILLOW AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1170 WILLOW AVE City NAPA Zip 945993091

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 006082013000

*P3a. Description:

- Style(s): American Colonial Revival
- Stories: 2
- Cladding: wood clapboards
- Porch: entrance porch, wood posts, wood rail
- Door(s): double, wood, divided lights, partially glazed
- Windows: Type 1 - single, double hung, wood, multipane top sash, shutters
- Roof: cross gable, composition shingle
- Chimney: none visible
- Related Features: detached 1-car garage
- Alterations: none visible
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

West elevation
ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both
c. 1885, architectural estimate

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.
Pier 9, The Embarcadero
San Francisco, California 94111

*P9. Date Recorded: January 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic
Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) *Required Information

PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 7N

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1177 WILLOW AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1177 WILLOW AVE City NAPA Zip 945592101

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) _____ APN 006081006000

*P3a. Description:

- Style(s): Craftsman
- Stories: 1 1/2
- Cladding: wood drop channel, wood shingles
- Porch: partial width, wood steps, wood piers
- Door(s): single, wood, paneled, wood screen
- Windows: Type 1 - canted bay, double hung, wood, multipane top sash, historic surround; Type 2 - tripartite, casement, wood, historic surround; Type 3 - tripartite, double hung, wood, historic surround
- Roof: side gable, composition sheets, brackets, exposed rafter tails, open eaves
- Chimney: none visible
- Related Features:
- Alterations: none visible
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

East elevation

ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1900, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: January 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):

PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1195 WILLOW AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1195 WILLOW AVE City NAPA Zip 945592101

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 006081004000

*P3a. Description:

- Style(s): American Colonial Revival
- Stories: 2
- Cladding: aluminum
- Porch: partial width, wood steps, wood columns, iron
- Door(s): single, partially glazed
- Windows: Type 1 - paired, double hung, vinyl, shutters; Type 2 - single, hopper, vinyl; Type 3 - canted bay, double hung, vinyl
- Roof: front gable, composition shingle, dormers
- Chimney: none visible
- Related Features: attached 2-car garage
- Alterations: cladding altered, door replaced, windows replaced
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

East elevation

ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1900, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: January 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) *Required Information

State of California -- The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 1197 WILLOW AVE

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 1197 WILLOW AVE City NAPA Zip 945592101

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 006081003000

*P3a. Description:

- Style(s): Minimal Traditional
- Stories: 1
- Cladding: wood clapboards, wood decorative shingles
- Porch: partial width, concrete steps, wood posts, wood rail
- Door(s): single, wood, paneled
- Windows: Type 1 - single, fixed, material unknown; Type 2 - single, double hung, material unknown
- Roof: side gable, composition shingle, open eaves
- Chimney: brick, interior
- Related Features: detached 1-car garage
- Alterations: windows replaced
- Notes:

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

North elevation

ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

1941, Napa City & County records

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: January 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) ***Required Information**

PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 47 WINDING WAY

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 47 WINDING WAY City NAPA Zip 94939

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 045090002000

*P3a. Description:

- Style(s): Modernism, Mid-Century
- Stories: 2
- Cladding:
- Porch:
- Door(s): double, metal, fully glazed
- Windows: Type 1 - single, sliding, aluminum; Type 2 - casement, vinyl
- Roof: flat, wide eaves
- Chimney: none visible
- Related Features: Parking lots, integral landscape and hardscape
- Alterations: some windows replaced
- Notes: Large apartment complex with multiple buildings; other buildings not visible from public right-of-way

*P3b. Resource Attributes: (List attributes and codes) HP3. Multiple family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

East elevation
ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: January 2011

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):
DPR 523A (1/95) *Required Information

PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6Z

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or #: (Assigned by Recorder) 0

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Napa and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; _____ B.M.

c. Address 0 City _____ Zip 945590660

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) _____ APN 006085007000

*P3a. Description:

• Notes: Public park

*P3b. Resource Attributes: (List attributes and codes) _____

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph



P5b. Description of Photo:

West elevation _____

ARG, January 2011

*P6. Date Constructed/Age and Source:

Historic Prehistoric Both

*P7. Owner and Address:

Not recorded

*P8. Recorded by: K. Horak/A. Lyons/M. Davis

Architectural Resources Group, Inc.

Pier 9, The Embarcadero

San Francisco, California 94111

*P9. Date Recorded: _____

*P10. Survey Type: Intensive

*P11. Report Citation: Alta Heights Historic

Context Statement and Survey Report

*Attachments: NONE Location Map Continuation Sheet Building, Structure, and Object Record Archaeological Record
 District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List):

DPR 523A (1/95)

*Required Information

Alta Heights Historic Context Statement and Survey Report

City of Napa, California



Pier 9, The Embarcadero | San Francisco, CA 94111
415.421.1680 | 415.421.0127 fax

San Francisco | Pasadena | Portland